


ARTIS, ATOS AND DITO CROSSES FOR ITEM










ATOS – LL & LRL luminaire mounting





The light source contained in this luminaire must only be replaced by the manufacturer or its authorised service agent or a person with equivalent qualifications.


0689_5004_C_

ECLATEC S.A.S. 41, rue Lafayette - PO Box 20069 - Maxéville - 54528 LAXOU CEDEX – France Tel. • +33 (0)3 83 39 38 00
Website • www.eclatec.com

ARTIS and DITO – Specific luminaire mounting







The light source contained in this luminaire must only be replaced by the manufacturer or its maintenance agent or a person with equivalent qualifications.

ECLATEC S.A.S. 41, rue Lafayette - PO Box 20069 - Maxéville - 54528 LAXOU CEDEX – France Tel. • +33 (0)3 83 39 38 00
Website • www.eclatec.com