


ORIENTIS







IP66





RoHS

220–240 V 50 Hz

	IK	 kg	SCx
With dome	10	7.6 kg	0.12 m²
Without dome	10	5.8 kg	0.1 m²

Top 60


Top 76

The light source contained in this luminaire must only be replaced by the manufacturer or its authorised service agent or a person with equivalent qualifications.








0730_5000_A

ECLATEC S.A.S. 41, rue Lafayette - CS 20069 - Maxéville - 54528 LAXOU CEDEX - France - Tel. • + 33 (0)3 83 39 38 00 - Website • www.eclatec.com




1



+








The light source contained in this luminaire must only be replaced by the manufacturer or its authorised service agent or a person with equivalent qualifications.



The DALI wires at the base of the pole must be separated and insulated if they are not connected.

4 Installation and maintenance



The light source contained in this luminaire must only be replaced by the manufacturer or its authorised service agent or a person with equivalent qualifications.